

INFORMATIONEN ZUR SICHEREN VERWENDUNG VON SVHCs

REACH ARTIKEL 33 INFORMATIONEN ZU BESONDERS BESORGNISERREGENDEN STOFFEN

Sehr geehrte Kundin, sehr geehrter Kunde,

Artikel 33(1) der REACH-Verordnung (Verordnung EG 1907/2006) informiert Kunden über zu treffende Risikomanagementmaßnahmen bei in Produkten enthaltenen SVHCs, besonders besorgniserregenden Stoffen, die im Verzeichnis der für eine Zulassung in Frage kommenden Stoffe aufgeführt sind, um deren sichere Verwendung zu gewährleisten.

FORD unterstützt die Ziele von REACH im Allgemeinen und Artikel 33(1) insbesondere. Sie entsprechen unserer eigenen Verpflichtung zu verantwortungsvoller Herstellung, Handhabung und Verwendung unserer Produkte.

Identifizierung von SVHCs

Nach bestem Wissen und gemäß den Informationen unserer Lieferkette und unseren eigenen Produktdaten sind alle SVHCs, die zu mehr als 0,1 % in Bestandteilen enthalten sind, auf der entsprechenden „SVHC-Liste“ für das jeweilige Fahrzeug/Teil aufgeführt.

Spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten

Falls erforderlich, werden spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten, der entsprechenden „SVHC-Liste“ für das jeweilige Fahrzeug/Teil hinzugefügt.

Allgemeine Informationen zur sicheren Verwendung von Artikeln

Zu jedem Fahrzeug von FORD gehört ein Handbuch, das Informationen zur sicheren Verwendung für Besitzer/Fahrer des Fahrzeugs enthält. Die Informationen von FORD zur Reparatur und Wartung von Fahrzeugen und Originalteilen umfassen auch Informationen über die sichere Verwendung für Servicemitarbeiter.

Sofern in Teilen dieses Fahrzeugs vorhanden, werden die SVHCs, die auf der entsprechenden „SVHC-Liste“ für das spezifische Fahrzeug/Teil angegeben sind, so eingebaut, dass die potenzielle Exposition gegenüber den Kunden minimiert und Gefahren für Mensch und Umwelt ausgeschlossen werden können, sofern das Fahrzeug und seine Teile bestimmungsgemäß verwendet werden und Reparaturen, Wartungen und Instandhaltungen gemäß den technischen Anweisungen für diese Tätigkeiten und nach den Industriestandards erfolgen.

Altfahrzeuge dürfen in der EU nur legal in zugelassenen Verwertungsanlagen entsorgt werden. Die Entsorgung von Fahrzeugteilen muss gemäß den geltenden lokalen Gesetzen und behördlichen Anweisungen erfolgen.

Modell: Ford Tourneo Connect

SVHC-Liste basierend auf ECHA-Kandidatenliste vom 1. Januar 2026

Spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten

Spezifische Informationen zur sicheren Verwendung nicht erforderlich – den allgemeinen Informationen zur sicheren Verwendung von Artikeln folgen.

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methylimidazole [693-98-1]
	Bumetrizole [3896-11-5]
	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Air Induction	Lead [7439-92-1]
Auto Transmission	Lead [7439-92-1]
Auto Transmission Shifter	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Body and Security Electronics	1,2-Dimethoxyethane [110-71-4]
	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Brakes	2-Methylimidazole [693-98-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	TBBA [79-94-7]
Bumpers and Spoilers	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]

	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Closures and Lids Mechanisms	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Clutch and DMF	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Triphenyl-phosphate [115-86-6]
Dressed Engine	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Octamethylcyclotetrasiloxane [556-67-2]
	TBBA [79-94-7]
Driveline	2-Methylimidazole [693-98-1]
	Lead [7439-92-1]
Driveline (Powerpack)	Lead [7439-92-1]
Driver Controls	Lead [7439-92-1]
Dynamic Sealing	Octamethylcyclotetrasiloxane [556-67-2]
EDS	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Exhaust (Powerpack)	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Exterior Lighting	Dicyclohexyl-phthalate [84-61-7]
	Lead [7439-92-1]
	TBBA [79-94-7]
Fuel	Alkanes, C14-17, chloro [85535-85-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	TBBA [79-94-7]
Functional and Black Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Hybrid Technology	Bumetrizole [3896-11-5]
	Dioctyltin dilaurate [3648-18-8]
	Lead [7439-92-1]
I/S Mirror	Lead [7439-92-1]
Interior Trim	Lead [7439-92-1]
	TBBA [79-94-7]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]

	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Lower Body Structure	Lead [7439-92-1]
Manual Transmission	Lead [7439-92-1]
Manual Transmission Shifter	Lead [7439-92-1]
Mirrors	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
others	1,2-Dimethoxyethane [110-71-4]
	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	1,3-Propanesultone [1120-71-4]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	2-Methylimidazole [693-98-1]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Bumetrizole [3896-11-5]
	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
	Dicyclohexyl-phthalate [84-61-7]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Lead-monoxide [1317-36-8]
	Melamine [108-78-1]
	Methyloxirane [75-56-9]
	N,N-Dimethylacetamide [127-19-5]
	N,N-Dimethylformamide [68-12-2]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Refractory ceramic fibres [142844-00-6]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Power Supply	Lead [7439-92-1]

Powertrain Controls and Calibration	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Powertrain Mounts	Lead [7439-92-1]
Restraint	Lead [7439-92-1]
Safety Electronics	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
Seating	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	Melamine [108-78-1]
Side Door Mechanisms	Boric acid [10043-35-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Side Doors BIW	Bumetrizole [3896-11-5]
Steering	Lead [7439-92-1]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
Suspension Frames and Mountings	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Wash-Wipe	Lead [7439-92-1]