

INFORMATIONEN ZUR SICHEREN VERWENDUNG VON SVHCs

REACH ARTIKEL 33 INFORMATIONEN ZU BESONDERS BESORGNISERREGENDEN STOFFEN

Sehr geehrte Kundin, sehr geehrter Kunde,

Artikel 33(1) der REACH-Verordnung (Verordnung EG 1907/2006) informiert Kunden über zu treffende Risikomanagementmaßnahmen bei in Produkten enthaltenen SVHCs, besonders besorgniserregenden Stoffen, die im Verzeichnis der für eine Zulassung in Frage kommenden Stoffe aufgeführt sind, um deren sichere Verwendung zu gewährleisten.

FORD unterstützt die Ziele von REACH im Allgemeinen und Artikel 33(1) insbesondere. Sie entsprechen unserer eigenen Verpflichtung zu verantwortungsvoller Herstellung, Handhabung und Verwendung unserer Produkte.

Identifizierung von SVHCs

Nach bestem Wissen und gemäß den Informationen unserer Lieferkette und unseren eigenen Produktdaten sind alle SVHCs, die zu mehr als 0,1 % in Bestandteilen enthalten sind, auf der entsprechenden „SVHC-Liste“ für das jeweilige Fahrzeug/Teil aufgeführt.

Spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten

Falls erforderlich, werden spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten, der entsprechenden „SVHC-Liste“ für das jeweilige Fahrzeug/Teil hinzugefügt.

Allgemeine Informationen zur sicheren Verwendung von Artikeln

Zu jedem Fahrzeug von FORD gehört ein Handbuch, das Informationen zur sicheren Verwendung für Besitzer/Fahrer des Fahrzeugs enthält. Die Informationen von FORD zur Reparatur und Wartung von Fahrzeugen und Originalteilen umfassen auch Informationen über die sichere Verwendung für Servicemitarbeiter.

Sofern in Teilen dieses Fahrzeugs vorhanden, werden die SVHCs, die auf der entsprechenden „SVHC-Liste“ für das spezifische Fahrzeug/Teil angegeben sind, so eingebaut, dass die potenzielle Exposition gegenüber den Kunden minimiert und Gefahren für Mensch und Umwelt ausgeschlossen werden können, sofern das Fahrzeug und seine Teile bestimmungsgemäß verwendet werden und Reparaturen, Wartungen und Instandhaltungen gemäß den technischen Anweisungen für diese Tätigkeiten und nach den Industriestandards erfolgen.

Altfahrzeuge dürfen in der EU nur legal in zugelassenen Verwertungsanlagen entsorgt werden. Die Entsorgung von Fahrzeugteilen muss gemäß den geltenden lokalen Gesetzen und behördlichen Anweisungen erfolgen.

Modell: Ford Transit / Tourneo Custom

SVHC-Liste basierend auf ECHA-Kandidatenliste vom 1. Januar 2026

Spezifische Informationen zur sicheren Verwendung von Artikeln, die SVHCs enthalten

Spezifische Informationen zur sicheren Verwendung nicht erforderlich – den allgemeinen Informationen zur sicheren Verwendung von Artikeln folgen.

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Appliques (Pillar, Decklid, Roof)	Lead [7439-92-1]
Auto Transmission	Lead [7439-92-1]
Auto Transmission Shifter	C,C'-azodi(formamide) [123-77-3]
	Dodecamethylcyclhexasiloxane [540-97-6]
Axle	Lead [7439-92-1]
Body and Security Electronics	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	2-Methylimidazole [693-98-1]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
Body Covers and Ornamentation	Bumetrizole [3896-11-5]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Body Side Interior Trim (Hard Trim)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Brakes	Diboron-trioxide [1303-86-2]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	TBBA [79-94-7]
Bumpers and Spoilers	Lead [7439-92-1]
Climate	1,2-Dimethoxyethane [110-71-4]

	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]
	Diboron-trioxide [1303-86-2]
	Hexahydromethylphthalic-anhydride [25550-51-0]
	Lead [7439-92-1]
Closures and Lids BIW	Lead [7439-92-1]
Closures and Lids Mechanisms	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Dressed Engine	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Octamethylcyclotetrasiloxane [556-67-2]
Driveline	Sodium borate, decahydrate [1303-96-4]
	Triphenyl-phosphate [115-86-6]
Driveline (Powerpack)	Lead [7439-92-1]
Driver Controls	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
EDS	4,4'-Isopropylidenediphenol [80-05-7]
	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Exhaust Cold End	Decamethylcyclopentasiloxane [541-02-6]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
Fixed Glass	Bumetrizole [3896-11-5]
Fuel	Lead [7439-92-1]
	TBBA [79-94-7]
Fuel Door	Lead [7439-92-1]
Functional and Black Trim	Lead [7439-92-1]
Glass And Channel Assy - Front/Rear	C,C'-azodi(formamide) [123-77-3]
Hybrid Technology	Boric acid [10043-35-3]
	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
I/S Mirror	Lead [7439-92-1]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]

	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]
	C,C'-azodi(formamide) [123-77-3]
	Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
	Lead [7439-92-1]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Imidazolidine-2-thione [96-45-7]
Latches - Side Door/Latch Mini Module	Lead [7439-92-1]
Locks	Lead [7439-92-1]
Manual Transmission	Triphenyl-phosphate [115-86-6]
Manual Transmission Shifter	Lead [7439-92-1]
Mirrors	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Triphenyl-phosphate [115-86-6]
Overhead Console	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
Pedals	Bumetrizole [3896-11-5]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Powertrain Controls and Calibration	Boric acid [10043-35-3]
	Lead [7439-92-1]
Powertrain Mounts	Lead [7439-92-1]
PT Sensors	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Safety Electronics	1,2-Dimethoxyethane [110-71-4]
	Lead [7439-92-1]
	TBBA [79-94-7]
Seating	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
	Sodium borate, decahydrate [1303-96-4]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]

Seats - Foam - Cut and Sew	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
Side Door Mechanisms	Bumetizole [3896-11-5]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Side Doors BIW	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Steering	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Suspension Frames and Mountings	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Transmission - Manual	Triphenyl-phosphate [115-86-6]
Wash-Wipe	Boric acid [10043-35-3]
	Lead [7439-92-1]
Wheels Tires Jacks and Equipment	Lead [7439-92-1]
Wiper Assembly (Rear, Front) & Washer System	Lead [7439-92-1]